

## REFERENCES

### Hydride Reorientation (HRT) Occurrence and Affects:

R. L. Sindelar and M. R. Louthan, Jr. and B. D. Hanson, "[White Paper Summary of 2nd ASTM International Workshop on Hydrides in Zirconium Alloy Cladding](#)"; June 10-12, 2014 Jackson, WY; May 29, 2015, FCRD-UFD-2015-000533, SRNL-STI-2015-00256

M.C. Billone, T.A. Burtseva, Z. Han and Y.Y. Liu, "[Embrittlement and DBTT of High- Burnup PWR Fuel Cladding Alloys](#)"; Argonne National Laboratory, September 30, 2013, FCRD-UFD-2013-000040, ANL-13/16, FCRD-UFD-2013-000401

### Behavior of HBF Under Normal Conditions of Transport:

#### 1) Cyclic Testing of Irradiated Fuel

Jy-An Wang and Hong Wang, "[Mechanical Fatigue Testing of High-Burnup Fuel for Transportation Applications](#)"; NUREG/CR- 7198 ORNL/TM-2014/214, October 2014

#### 2. Sandia Shaker Table and Over-the-Road Vibration Studies

K Sorenson, P. McConnell G. Flores, "[Fuel Assembly Vibration/Shock Test Simulating Normal Truck Transport](#)"; NEI Used Fuel Management Conference, May 7-9, 2013, St. Petersburg, Florida

Paul McConnell, "[Fuel-Assembly Shaker Test Plan- Tests for Determining Loads on Used Nuclear Fuel under Normal Conditions of Transport](#)"; September 30, 2012 FCRD-UFD-2012-000341, SAND2012-8323P

P. McConnell, R Wauneka, S Saltzstein, K Sorenson, "[Normal Conditions of Transport Truck Test of a Surrogate Fuel Assembly](#)"; SAND2014-20495, FCRD UFD-2014-000066, Revision 0.1 (December 15, 2014)

### Confirming the Condition of HBF during Extended Storage

Hundal Jung, Pavan Shukla, Tae Ahn, Lynn Tipton, Kaushik Das, Xihua He, Debashis Basu, "[EXTENDED STORAGE AND TRANSPORTATION: EVALUATION OF DRYING ADEQUACY](#)", June 2013

Electric Power Research Institute, [High Burnup Dry Storage Cask Research and Development Project-Final Test Plan](#)", February 27, 2014